

**3. LOW WATER PRESSURE INVESTIGATION –  
HARAKEKE STREET**

RR 10112

A report from the Water Services Customer Services Manager advised members of the steps taken by Council staff to source the apparent “loss of water pressure/flow” experienced by some of the residents in the northern section of Harakeke Street beyond Rochdale Street.

It was **decided**:

1. That the resident owners be advised that on the investigations carried out to date, it would appear that the supply lines within the properties need to be either replaced and/or upgraded to improve the supply into their residences.
2. That no additional supply pipeline be laid across Harakeke Street at this stage to interconnect with the existing 40mm diameter submain, but that further consideration be given to increasing the pressure/flow in the area, should the problem remain after the private owners have “upgraded and/or replaced” the defective pipelines within their own premises.