12. RIGHT TURN PHASE AT CRANFORD STREET/ MAIN NORTH ROAD

The Signals Engineer reported on the reason for the non-filtering of the right turn phase at the Cranford/Main North intersection. There was some discussion on the workings of the intersection, other changes in the area and the delays often experienced by right turning traffic. The Board **received** the information and asked that the City Streets Unit arrange for the video camera to be stationed at the intersection for a full Saturday, with a report to be made to the 30 June 1999 meeting.