## 6. FLAY CRESCENT-REQUEST FOR TRAFFIC CALMING

The results of the monitoring of driver behaviour in Flay Crescent over the last three months were reported, having been requested by the Board in March 1998.

The Board was advised that the Papanui Police had regularly patrolled the area and latest feedback from the residents was that the problem had now quietened down considerably. In addition a speed survey had been undertaken with the result that the 85 percentile speed was 53 kph.

Traffic calming measures were not favoured, however because of the severe nature of two of the corners in the street, permanent curve warning signs were considered appropriate.

Accordingly, the Board **decided** that permanent curve warning signs be installed outside Nos 3 and 32 Flay Crescent facing to the north-east on the approaches to the corners opposite Nos 16 and 22 Flay Crescent.