

7. WHITEHALL STREET TRAFFIC PROBLEMS

As a result of concerns expressed by a resident in Whitehall Street, the Area Engineer reported on investigations into traffic speed problems in the street. It was noted that the Mairehau South LATMS proposed threshold treatments for each end of the street. Speed checks had been carried out during the morning peak; traffic volumes were observed and were recorded as low. The Board **received** the information.