

## 5. LOW WATER PRESSURE INVESTIGATION – HARAKEKE STREET

The Board was provided with an update report on the steps recently taken to monitor the Council's mains supply pressure in Harakeke Street during the last summer period.

The investigation revealed no unacceptable pressure drops when compared to the initial investigation undertaken in July 1999.

The Board received the report and **decided** that the residents be advised that the Council's reticulation system in this area, having been investigated, showed that an adequate mains water supply was available in the northern section of Harakeke Street.