

5. DEPUTATIONS BY APPOINTMENT

5.2 CONDITION OF DYERS ROAD

Chrissie Williams addressed the Board, drawing attention to the rough condition of the road shoulder in Dyers Road, the narrow carriageway of the road with no room for cyclists and illustrated these points with coloured transparencies. Ms Williams believed that along much of Dyers Road there was spare land available alongside the roadside on to which the carriageway sealed could be extended. To make the situation even worse on Dyers Road, it is a 70 km/h speed area and part of the ring road system.

Ms Williams believed that attention is needed urgently to Dyers Road, within the next few months.

Ms Williams also urged that consideration be given to making provision along Dyers Road for separate cycle lanes.

Ms Williams asked the Board to consider supporting this project in its forthcoming recommendations to the Council's five year Capital Works Programme.

The Board agreed to consider this request at its forthcoming Capital Works Projects Meeting.