

7. QUEEN ELIZABETH II POOLS REDEVELOPMENT - PROGRESS REPORT

Mark Noonan (Project Co-ordinator) updated the Committee on progress with the Queen Elizabeth II Pools redevelopment project. He reported on two outstanding issues raised by Committee members following the site visit before the August Committee meeting:

1. Windows to the north wall of the mezzanine floor - The windows have not been included in the wall until the use of the floor has been determined.
2. Dive pool ceiling – Because of budget constraints, the replacement of the dive pool ceiling and the associated lighting and HVAC (heating, ventilation and air conditioning) system have never been part of this project. Estimated costs being:

To replace the existing PVC ceiling with perforated, corrugated aluminium to match the adjacent leisure pool	\$394,000
--------------------------------------------------------------------------------------------------------------	-----------

To replace the existing HVAC system (present system needs replacing in the next three to five years)	\$460,000
------------------------------------------------------------------------------------------------------	-----------

The Committee **decided** that a report be prepared for the Council meeting, scheduled for 27 September 2001, outlining all outstanding items required to satisfactorily complete the project.