


11. TRUMAN ROAD OAK TREE



Concerns received from the residents of No's 51 and 53 Truman Road with regards to the Oak tree located in the footpath between their driveways were set out in a report from the Parks and Waterways Area Advocate.

Several photographs were presented showing the positioning of the tree and the accompanying report elaborated on the residents concerns including difficulty for drivers having adequate site lines when reversing from the properties. Damage to driveways and to the footpath and kerb were other concerns.

Mr N Packman, of 53 Truman Road elaborated on the concerns including those of his neighbours.

Possible remedial steps including the realignment of the driveway at no 51 were noted.

The Board **decided** to recommend to the City Services Committee:

1. That the tree outside No's 51 and 53 Truman Road not be removed.
2. That the Parks and Waterways Unit be requested to offer whatever assistance it can give the residents in realigning their driveways to give better clearance from the tree.