

31. HAWKINS/LOWER STYX/MARSHLAND ROADS INTERSECTION

The Board considered a report from the City Streets Manager on the investigations into an option of installing traffic signals to address safety issues at the Hawkins Road/Lower Styx Road/Marshland Road intersection.

Board members raised concerns in relation to 'informal' slip lane on Marshland Road at the corner of Lower Styx Road, the sharpness of the left-hand turn into Hawkins Road from Marshland Road, obstructed sight lines and the possibility of people undertaking u-turns on Marshland Road near the intersection.

The Board **resolved**:

1. That the installation of traffic signals at this intersection not be pursued.
2. That staff proceed with the installation of safety work shown on Plan TP142401 subject to the Board's concerns being addressed.