


3. GARREG ROAD/GLANDOVEY ROAD INTERSECTION – RIGHT TURN LANE



The Board was presented with the investigation outcomes of an earlier Board request regarding the provision of a marked right turn lane into Garreg Road from Glandovey Road.

The survey results and the technical assessment subsequently undertaken showed that the number of turning movements occurring did not meet the criteria and as such an exclusive right turn lane could not be supported.

The Board **decided** that the information be received and no further action be taken.