


12. WORCESTER STREET BETWEEN LATIMER SQUARE AND MANCHESTER STREET



The Chairman spoke briefly regarding the ongoing maintenance problems being experienced with the bollards in Worcester Street. Mr Richard Bailey, Transport and City Streets Unit attended and briefed the Committee on the trials being undertaken with an alternative form of wheel stop to replace these. He indicated that it was expected a modified version would be installed within the next two weeks and that if this design is found to be satisfactory replacement of the existing bollards would then be undertaken.