## 11. BUCKLEYS ROAD – BUS STOP

Officer responsible	Author
City Streets Manager	Lorraine Wilmshurst, Area Engineer, DDI 372-2625
Corporate Plan Output: On Street Managemen	t

The purpose of this report is to ask the Board to recommend to the Council that the bus stop at Eastgate Mall be extended.

With the commencement of the Orbiter bus route and the changes made to the eastern bus routes at the end of last year it has been found that the present bus stop is not long enough to accommodate all the buses.

Currently there are two "all day" parks between the end of the bus stop and the access to the loading zone for the Mall. The removal of these two spaces will allow the bus stop to be lengthened to a distance that will accommodate the buses at this interchange.

**Recommendations:** That the Board recommend to the Council:

- 1. That the bus stop on the south east side of Buckleys Road commencing at appoint 217.5 metres from its intersection with Linwood Avenue and extending in a north east direction for a distance of 31.5 metres be revoked.
- 2. That a bus stop be installed on the south east side of Buckleys road commencing at appoint 217.5 metres from its intersection with Linwood Avenue and extending in a north east direction for a distance of 43 metres.

Chairman's	
<b>Recommendation:</b>	That the officer's recommendations be adopted.

