The Committee received a report from the Leisure Manager on the condition of the existing synthetic surface of the athletic track at Queen Elizabeth II Park, the options for its upgrading together with estimated costings.

The report concluded that maintenance and/or replacement of the QEII Park Athletic track is likely to cost between \$400,000 and \$800,000 during the next several years. Whilst it appears that sufficient budget provision has been made, it may be necessary to commence some repairs/replacement at an earlier date. Replacement of the high jump fan should be treated as a priority project.