

## 9. KAINGA ROAD

The Area Engineer reported, with information concerning frost problems experienced along Kainga Road during winter months and measures put in place to alleviate these problems. The Board **received** the information and asked that the Residents' Association be advised of the action taken.