

10. FLOODING IN MONCK'S BAY

The Board considered a report advising that a detailed report is being prepared to present proposals for addressing the lack of flow capacity in the Rifle Range Drain in Moncks Bay in major storm events.

The Board **received** the information.