

3. STANMORE ROAD – PARKING RESTRICTION

Officer responsible City Streets Manager	Author Lorraine Wilmshurst, Area Engineer
Corporate Plan Output: On Street Management	

The purpose of this report is to recommend that a P10 parking restriction be installed in Stanmore Road.

A restaurant has opened in the old bank building in Stanmore Road between Avalon Street and North Avon Road. The small amount of parking in the area is now being occupied for several hours at a time.

Parking restrictions have been imposed outside the businesses on the west side of Stanmore Road and this has shifted the problem to the businesses on the east side of the road.

To allow for a reasonable turnover in the parking area and access for customers to all the businesses in the area a parking restriction needs to be imposed on the east side of the road.

A P10 parking restriction from the build out for the pedestrian crossing to the taxi stand would alleviate the parking difficulties being experienced at present.

Recommendation: That the parking of vehicles be restricted to a maximum of 10 minutes on the east side of Stanmore Road commencing at a point 14.5 metres from its intersection with Siddal Place and extending in a southerly direction for a distance of 5.5 metres.