

1. **KILMORE STREET – TOUR COACH AND SHUTTLE BUS STOP** RR 8759

| | |
|--|---|
| Officer responsible City Streets Manager | Author Lorraine Wilmshurst, Area Engineer |
| Corporate Plan Output: Traffic Signs and Markings | |

The purpose of this report is to recommend to the Council that a tour coach and shuttle bus stop be installed in Kilmore Street.

The Residents Association requested that an investigation be carried out into the double parking that is occurring in Kilmore Street outside the backpacker hostel. During rush hour traffic the tour coach and shuttle buses block the left hand lane and reduce the traffic flow along this section of road.

To eliminate the traffic problem that is being created by the double parking of the tour coach and the shuttle buses it is recommended that a tour coach and shuttle bus parking restriction be imposed outside the backpacker hostel.

Recommendation: That a tour coach and shuttle bus stop be installed on the south side of Kilmore Street commencing at a point 52 metres from its intersection with Oxford Terrace and extending in an easterly direction for a distance of 7.5 metres.